

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Number:

6,940,281 B2

Issued:

September 6, 2005

Name of Patentee:

Peter Feenan, et al.

Title of Invention:

GRADIENT COIL APPARATUS AND METHOD OF ASSEMBLY

THEREOF

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR APPLICANTS' MISTAKE (37 C.F.R. 1.323)

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 Certificate
DEC 0 7 2005
Of Correction

ATTENTION:

Decision and Certificate of Correction Branch of the Patent Issue Division

Sir:

It is noted that errors appear in this patent of a typographical nature or character, as more fully described below. It occurred in good faith. Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination. A certificate of correction is requested.

Attached hereto, in duplicate, is Form PTO-1050, with at least one copy being

12/06/2005 ZJUHAR1 00000017 061130 6940281 01 FC:1811 100.00 DA

I certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on
12/01/05
(Date of Deposit)
Candace Kuper
(Name of Person Mailing Paper)
Cardace-Kuper 12/1/05 Signature Date

suitable for printing.

The errors are in the body of the patent in column 3, lines 1 and 32; column 4, line 58; column 5, line 12; and column 6, lines 5 and 15...

Please send the Certificate of Correction to:

Cantor Colburn LLP 55 Griffin Road South Bloomfield, Connecticut 06002

Please charge the amount of \$100.00, as required by 37 C.F.R. 1.20(a) or any additional charges with respect to this request or otherwise, to Deposit Account No. 06-1130 maintained by Patentees' attorneys.

Respectfully submitted,

CANTOR COLBURN LEP

By:_

David A. Fox

Registration No. 38,807

55 Griffin Road South

Bloomfield, Connecticut 06002 Telephone: (860) 286-2929

Customer No. 23413

Date: December 1, 2005

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,940,281 B2

DATED

: September 6, 2005

INVENTOR(S)

: Peter Feenan, et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 3,

Line 1, after "As" delete "shown tube 30," and insert therefor --shown, tube 30-.. Line 32, after "now" insert --be--.

Column 4,

Line 58, after "sheet" (second occurrence) insert --58--.

Column 5,

Line 12, after "70" insert --is shown --.

Column 6

Line 5, after "made" insert --and--. Line 15, after "etc." delete "are us".

MAILING ADDRESS OF SENDER:

Cantor Colburn LLP 55 Griffin Road South Bloomfield, CT 06002 PATENT NO. 6,940,281 B2

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,940,281 B2

DATED

: September 6, 2005

INVENTOR(S)

: Peter Feenan, et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 3,

Line 1, after "As" delete "shown tube 30," and insert therefor --shown, tube 30--. Line 32, after "now" insert --be--.

Column 4,

Line 58, after "sheet" (second occurrence) insert --58--.

Column 5,

Line 12, after "70" insert --is shown --.

Column 6,

Line 5, after "made" insert --and--. Line 15, after "etc." delete "are us".

MAILING ADDRESS OF SENDER:

Cantor Colburn LLP 55 Griffin Road South Bloomfield, CT 06002 PATENT NO. 6,940,281 B2